



Wilson  
Creek  
Watershed  
Restoration  
Mt Rogers  
NRA



# Wilson Creek Watershed Restoration Mt Rogers NRA









# Wilson Creek Watershed





VA Highland  
Horse Trail  
Crossing –  
reduce  
erosion at  
creek  
crossing





Reduce  
erosion on  
trails





Build fence  
around  
seeps and  
high  
elevation  
bogs





Spruce  
Restoration:  
spruce  
release and  
cone  
collection –  
20 acres,  
2,000  
seedlings





Partners:

USFS

EBTJV

Grayson

Highlands SP

Trout Unlimited

VDGIF

ATC

TNC

Southern

Highlands

Reserve

Blue Ridge

Discover Center





New Endangered  
Species  
confirmed in  
Spruce  
ecosystem –  
Rusty Patched  
Bumblebee!!

